


AKKU-BOHRMASCHINE

SX2000----A

TYPE 1



©

AKKU-BOHRMASCHINE

SX2000----A

TYPE 1



Pos. Nr	Ersatzteilnummer	Beschreibung	Preis	Variants
1	1	149518-01	SCHRAUBE	
2	1	419233-00	SPANNBOHRFUTTER	
3	1	5104564-00	GETRIEBE ZSB	
4	2	311940-02	SCHRAUBE	
5	1	5102346-00	MOTOR + ZW.GETR.	
6	1	5104553-00	ANTRIEB	
7	1	5104567-00	SCHALTER	
8	1	5104580-00	GEHAEUSEPAAR	
9	1	5104546-00	TYPENSCHILD	JP
10	1	148354-03	HALTER	
11	1	419581-05	SCHRAUBENZIEHERBIT	
12	1	5106149-00	BAND	
13	1	5100976-02	ANSCHLUSSBLOCK	
14	1	5104632-00	EINSATZ	
15	1	5104635-00	LADEGER. + HALTER	
16	1	5104547-00	AUFKLEBER	
17	2	311993-00	SCHRAUBE	
18	6	5100814-03	SCHRAUBE	
19	1	499948-03	ACCU-PACK	
19	1	5100294-07	ACCU-PACK 9.6V	JP